


YEAR
1995-96
1996

MODEL
2.5TL
3.2TL

VIN APPLICATION
ALL

BULLETIN NO.
96-035



Static When Adjusting the Radio Volume

PROBLEM

Static comes from the speakers when the radio volume is first adjusted. The noise coincides with the movement of the volume knob, and will usually stop after a few consecutive movements of the knob. The problem may recur when the volume knob is readjusted after the vehicle has been sitting for several hours.

CORRECTIVE ACTION

Replace the radio with a remanufactured unit listed under PARTS INFORMATION.

NOTE: All remanufactured units have been improved to eliminate this problem.

PARTS INFORMATION

Auto Radio Tuner Assembly: P/N
39100-SW5-A00RM

WARRANTY CLAIM INFORMATION

In warranty: The normal warranty applies.

Operation number: 010150

Flat rate time: 0.7 hour

Failed P/N: 39100-SW5-A00

Defect code: 032

Contention code: F99

Template ID: 96-035A

Out of warranty: Any repair performed after warranty expiration may be eligible for goodwill consideration by the District Technical Manager or your Zone Office. You must request consideration, and get a decision, before starting work.