



Over the Air System Updates

December 12, 2018

2019 RDX: Software Update Display Audio/Navigation Available

INTRODUCTION


The latest software contains system enhancements and bug fixes for a number of rarely found problems.

INSTALLATION DETAILS

NOTE: For more information on how to do a software update, see System Updates in the online owner's manual or <http://owners.acura.com/vehicles/information/2019/RDX/features/system-updates>

- The software download will take about 30 minutes.
- The vehicle can be used normally even while updates are being downloaded or updated.
- Depending on your vehicle trim, some enhancements/bug fixes may not be applicable.

Go to System Updates on the Home screen in your vehicle to start the update.



NEW SOFTWARE VERSION D.1.0.7

The new software contains the following enhancements and rare bug fixes.

- *Bluetooth*® audio song text information is cropped and misaligned when changing songs.
- After creating a TuneMIX, then adding an additional preset, the options that appear in the top of the screen are cut off.
- When changing *Bluetooth*® connected phones, the device name does not match what is currently connected.
- The display is frozen and requires cycling the ignition to recover.
- Improvement while scrolling through *Bluetooth* Audio media items on a Google Pixel 2 phone.
- Incorrect maneuver icon is shown on the head-up display (HUD). The **Navigation** application shows that there is another maneuver direction, while the head-up display shows that the next maneuver is the destination flag icon.

- After arriving at a destination and driving offline from the Connected Features, the last maneuver text is still displayed.
- The Route Overview shows entire world map, instead of the proper map scale when displaying the entire route.
- Navigation application voice-guidance says to take incorrect named roads.
- Improves speed of switching *Bluetooth*® profiles.
- When selecting the Navigation Turn List, the Route Overview is shown.
- Fixes discrepancy between actual radio frequency and displayed frequency on Secondary display.
- On stacked roads, the vehicle position jumps to the lower road after making a maneuver on the upper road.
- *Bluetooth*® Audio cuts out.
- Navigation Nearby button is corrected to display consistent text.
- **Siri Not Available - Internet Connection Lost** response mitigated.
- The Notification bar will indicate when an over the air update is available.
- **Message Sent** text remains on the head-up display.
- A black screen appears in the secondary display information for the Navigation application.
- When exiting the **Settings** menu, a pop-up message appears that says **Settings Saved** even if no setting was changed.
- Predefined SMS (short message service) texts do not change when changing the system language.
- A route calculation failed error is displayed on the head-up display when cancelling the route on the center screen.
- SiriusXM® Radio will play after changing the audio app to USB in the Primary display information area, when Apple CarPlay® is displayed in the Secondary information area.
- A route calculation failed error is displayed on the head-up display when setting a new route on the center screen, even if the route was successfully calculated.
- Route guidance to waypoints and previous routes will not resume after long Ignition cycles (greater than 30 sec).
- On the **Map Update Instructions** screen, a message displays ..., rather than the actual URL for map updates.
- Navigation routing guidance avoids the use of alleys when possible.
- When using CarPlay and the phone is left connected to the vehicle, a message stating **Unable to start CarPlay** will appear after an ignition cycle.
- In the Navigation application under Downloaded Places, the wrong point of interest (POI) will be deleted if more than one POI was previously downloaded.
- When displaying distance, the correct abbreviation for meters is not displayed.
- When the system language is set to anything other than English, AcuraLink features show as HondaLink®.
- On the map screen, the street name balloon overlaps with the next maneuver guidance arrow.
- User unable to retrieve a POI that was confirmed by the system to have been downloaded while the vehicle was off.
- When the Navigation app is in the offline mode and an address is searched for using voice recognition, it causes an Android has stopped notification.
- CarPlay ID unavailable for an entire ignition cycle.
- When inserting a USB flash drive and opening the USB media app, a message stating **No Device Connected** appears.
- Device phone name will display as Unknown when a device phone is connected via *Bluetooth*®, and a second device phone is used for CarPlay.

- Navigation Connected Feature services (traffic, POI search and routing) are unavailable after the initial attempt.
- When connected to CarPlay, accessing the phone profile settings from a different device (without making any changes), the screen will get stuck showing **Updating** soon after selecting **Apply Changes**.
- Navigation routing guidance avoids the use of gated off roads that are not publicly accessible.
- Voice and maneuver guidance will not indicate a U-turn when routing through Waypoints where the maneuver is needed.
- Receiving a text message, the contact's name on the head-up display will show incorrectly as the Last Name, First Name + Last Name.
- There is a mismatch on the center screen and meter for the distance to the next maneuver, after a route calculation near a road intersection.
- The AM radio frequency does not show in the secondary display information area
- The Navigation app updates the next maneuver icon, 1 second before updating the text.
- A sharp left turn maneuver guidance is given instead of a U-turn maneuver.
- When tuning to FM source, turning the vehicle off then turning it back on in less than five minutes; the FM audio source does not resume and the Secondary display information shows loading until the source is changed or audio is turned off then on again.
- System will display HD Radio logo in areas not covered by HD Radio.