

Tech	Qty.	Part Number	Description	Each	Total	Date	11-04-2011	Mileage	155321	Invoice	56366
------	------	-------------	-------------	------	-------	------	------------	---------	--------	---------	-------

MLN Engine quit on customer while driven on x-way, customer reports long history of excessive oil consumption. When engine is cranked and started is very loud and may have internal damage. Investigate concern and advise on best course of action for repair.

Technician found that the engine has major blow by. A piston or two may have a hole in it. At this point, technician believes that the least costly thing to do would be to replace the engine with a used engine.

Subtotal for Replace engine timing belt, serpentine b 105.00

MLN			Replace the Engine with a used engine		2,520.00
MLN	1	*	Used engine (92k miles/1 year warranty on parts and labor)	2,175.00	2,175.00
MLN	2	91213-R70-	Cam seal	9.92	19.84
MLN	1	91212-R70-	Crank seal, front	10.95	10.95
MLN	1	91214-RCA	Crank seal, rear	13.44	13.44
MLN	1	22105-PGE	Clutch kit	364.29	364.29
MLN	1	22810-PPT	Clutch release bearing	57.78	57.78
MLN	1	TB 329 K1	Timing belt kit	281.13	281.13
MLN	6	6994	Spark Plug	29.06	174.36
MLN	1	19200-RDV	WATER PUMP	203.40	203.40
MLN	1	14520-RCA	Timing belt tension adjuster	136.71	136.71
MLN	1	6PK-2135	Serpentine drive belt	43.92	43.92
MLN	1	*PART	misc parts, oil and filter, clamps, and hoses estimated amount.	150.00	150.00

Subtotal for Engine 6,150.82

Parts:

OEM remanufactured engine 6,000.00

Estimate for Parts 6,000.00

MLN			"PITSTOP" Inspection		0.00
			Test Drive		
			Engine - Maint. Required		0.00
			Transmission - Need More Time for Diagnosis		
			Lights (Interior/Exterior) - Good Condition		
			Wiper Blades - Good Condition		
			Guages/Warning Lights - Good Condition		
			Fluids		
			Engine Oil - Good Condition		
			Transmission Fluid - Good Condition		
			Power Steering Fluid - Good Condition		
			Cooling System - Maint. Required		0.00
			Freeze Point: - °F		
			Brake Fluid - Good Condition		
			Differential(s) - Need More Time for Diagnosis		
			Washer System - Need More Time for Diagnosis		
			Washer Fluid Full (0 Gallons Added)		

Model 2005 ACURA TL V6 3.2L, 3210cc, Gas, FI
License [REDACTED] **Color** Gray
Vin [REDACTED]
Home [REDACTED] **Phone 2** - -

Service History	Miles	Date	Next Service
Past Due= Red	Due Soon= Green		Not Due= Black

Warranty Code Information

Special Order parts that are returned are subject to a 20% restocking fee Shop Warranty is 2 years with UNLIMITED Miles on all new parts and labor services done on vehicles. Warranty excludes wear items used parts. Maintenance schedule must be followed to validate this warranty.

You are entitled by law to the return of all parts replaced, except those which are too heavy or large, and those required to be sent back to the manufacturer or distributor because of warranty work or an exchange agreement. You are entitled to inspect the parts which cannot be returned.

X:

Customer acknowledges receipt of merchandise and services.

Payments

Department Sale

Labor	2,775.00
Parts	3,480.82
Shop Supplies	33.33
Other	0.00
Enviromental fees	0.00
SUB TOTAL	6,289.15
Sales Tax	210.85
TOTAL	6,500.00
BALANCE	6,500.00

Thank you for your trust in us. We look forward to seeing you in the future. If you should have any questions or concerns about the repairs made to your vehicle please contact us.

Tech	Qty.	Part Number	Description	Each	Total	Date	11-04-2011	Mileage	155321	Invoice	56366
------	------	-------------	-------------	------	-------	------	------------	---------	--------	---------	-------

Under The Hood

Belts - Good Condition

Air Filter (if accessible) - Need More Time for Diagnosis

Battery (Visual Only) - Good Condition

Engine Mounts - Good Condition

Under The Car

Suspension/Steering - Good Condition

Fluid Leaks - Good Condition

Exhaust System - Good Condition

Wheels

Brakes (Visual Only) - Good Condition

Wheels (Bent/Damage) - Maint. Required 0.00

Tire Condition - Good Condition

Tire Tread Depths (Tires should be replaced at 3/32"):

LF 4.5/32"

RF 5.5/32"

LR 11.5/32"

RR 4/32"

Additional Inspection Results:

Pit Stop Inspection	0.00
----------------------------	-------------